

Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250 Tel: (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Richard Tyler MILBANK MANUFACTORING INC 1400 E. HAVENS ST. KOKOMO, IN 56901-3188

08/13/1998

NET Job Number:

98.05374

Page 1 of 3

Enclosed are the Analytical Results for the following samples submitted to NET, Inc. Indianapolis Division for analysis:

Project Description: TWICE WEEKLY WASTEWATER

Sample Date Number Sample Description Taken Received 2X WEEKLY COMP 08/04/1998 08/05/1998 214665

National Environmental Testing, Inc. certifies that the analytical results contained herein apply only to the specific samples analyzed.

Reproduction of this analytical report is permitted only in its entirety.

Project Representative

La Barrer



AUG 1 9 1998

Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250

Tel: (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Richard Tyler
MILBANK MANUFACTORING INC
1400 E. HAVENS ST.
KOKOMO, IN 56901-3188

08/13/1998

Job No.: 98.05374 Page 2 of 3

Date Received: 08/05/1998

Job Description: TWICE WEEKLY WASTEWATER

Sample Number	Sample Number / Sample I.D.				Analyst &		Reporting		
Parameters		Result	Flaq	Units	Date Analyzed	Method	Limit		
				pod tropes	. (25.5)				
214665	2X WEEKLY C	OMP		08/04/1998					
Iron, ICP		0.71		mg/L	psc / 08/10/1998	EPA 200.7	<0.10		
Lead, ICP		<0.080		mg/L	psc / 08/10/1998	EPA 200.7	<0.080		
Silver, ICP		<0.020		mg/L	psc / 08/10/1998	EPA 200.7	<0.020		
Zinc, ICP		0.072		mg/L	psc / 08/10/1998	EPA 200.7	<0.020		



AUG 1 9 1998

Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250

Tel: (317) 842-4261 Fax: (317) 842-4286

FIELD REPORT

JOB #: 98.05374

CLIENT: MILBANK MFG.

PROJECT: TWICE WEEKLY WASTEWATER

DATE: 8/05/98

SAMPLER(S): MTM/MEM

An ISCO model 3710 auto sampler was used in the composite mode of operation. The sampler was equipped with a plastic composite jug, tygon suction line, battery, ice, and strainer.

All reusable equipment is decontaminated with alconox, tap water, 5% nitric acid, and deionized water. New tygon suction tubing was used for the sampler. A stainless steel strainer was also used for the sampling event.

The sampler was set to take a sample every 30 minutes for 8 hours.

Monitoring start 7:30 on 8/04/98
Monitoring end 15:00 on 8/04/98

The composite sample was clear.

Notes: Samples were preserved, in the field, in the appropriate containers with any required preservative.



91998

CHAIN OF CUSTODY RECORD													
COMPANY Milbank MAN													
ADDRESS 1400 East Have	ns St. Kokomo IN	56901-3188											
PHONE 765 - 452-5694	FAX												
•													

THAT HAME)			PRO	PROJECT NAME/LOCATION 2x weekly wastewater PROJECT NUMBER PROJECT MANAGER													P.O. NO													
			ME MILL SIGNATURE				# and Type of Containers					*	Report	Poku		ANAL	YSES					To assist us in selecting the proper method Is this work being conducted for regulatory compliance monitoring? Is this work being conducted for regulatory enforcement action? Yes No								
DATE 1998	TIME		SAMPLE ID/DESCRIPTIO	N	MATRIX	GRAB	COMP	5	NaOH	E .	H ₂ SO ₄	ОТНЕВ	metals	Field R					•			-	Which re	gulations	····	UST _ Other _		Drinking	water Water None	
8/4/98	1	aγ ω	eekly- comp		ω		X			1			×	X								-	* me	tals	(Fe		ь, <i>Ад</i>			
											+																			
							+			+	+	+										-								
										1																				
CONDI	TION O	F SAMPLE:	BOTTI ES INTACT2	NEO/NO				1	C 65	_	1					ATO	V50-					1						-	N/A	
SAMPL	E REMA	AINDER DISP		SAMPLE REMA	INDE	ER TO	CLIE	AOI ENT	LATII VIA	LES	ERI	EE (JF H	EAD:	SPAC	E? Y	YES/I		NE	L 			MPERA ttles sup	plied b	y NET	REC	NO			
METHO	D OF S	HIPMENT	DATE TIME	REMAR	_				_				RE	LINQU	JISHED	BY:					8/5	198	TIME 15.	:35	FECEN.	led Fo	R NET BY:) w	th	
-	12													-/	-															

REPORT TO: MR. Richard Tyler

INVOICE TO: _____